



<b>Product Name: Broom-Blade Combo</b>				
<b>Summary of Product Application</b>	Sweeping hard surfaces, including footpaths, roads, and factories.			
<b>Hazards</b>	<b>Risk Assessment</b>			
	Probability	Exposure	Consequence	<b>Risk Level</b>
Moving parts	Unusual	Occasional	Serious	Mod/Substantial
Moving brush	Unusual	Occasional	First aid	Acceptable
Movement dust created by sweeping.	Very Likely	Occasional	Serious	Mod/Substantial
Flying debris	Likely	Occasional	Casualty	Moderate
Pinch points	Unusual	Occasional	First aid	Acceptable
<b>Control measures</b>	<ul style="list-style-type: none"> <li>• Ensure an appropriate respirator is used if the broom is generating dust.</li> <li>• Ensure that eye protection is used.</li> <li>• Keep clear of moving parts; do not try to touch the moving broom.</li> <li>• The greatest risk is to people working around the Dingo, rather than the operator. To eliminate risk, ensure that an effective barrier is created around the operating machinery.</li> </ul>			
<b>Residual Risk of Plant with Control Measures</b>	<ul style="list-style-type: none"> <li>• Acceptable</li> </ul>			
<b>Additional Safety Comments</b>	<ul style="list-style-type: none"> <li>• The risk assessment has been carried out using the NSCA Risk Score Calculator. For more information contact Dingo.</li> </ul>			



<b>Product Name: Broom-Bucket Combo</b>				
<b>Summary of Product Application</b>	Sweeping hard surfaces, including footpaths, roads, and factories.			
<b>Hazards</b>	<b>Risk Assessment</b>			
	Probability	Exposure	Consequence	Risk Level
Moving parts	Unusual	Occasional	Serious	Mod/Substantial
Moving brush	Unusual	Occasional	First aid	Acceptable
Movement dust created by sweeping.	Unusual	Occasional	Casualty	Mod/Acceptable
Flying debris	Unusual	Occasional	Casualty	Mod/Acceptable
Pinch points	Unusual	Occasional	First aid	Acceptable
<b>Control measures</b>	<ul style="list-style-type: none"> <li>• Ensure an appropriate respirator is used if the broom is generating dust.</li> <li>• Ensure that eye protection is used.</li> <li>• Keep clear of moving parts.</li> <li>• Do not attempt to remove blockages from the hood while the broom is rotating.</li> <li>• Ensure the broom hood is never removed.</li> <li>• Ensure that the safety instructions in the operation manual are always followed.</li> <li>• The greatest risk is to people working around the Dingo, rather than the operator. To eliminate risk, ensure that an effective barrier is created around the operating machinery.</li> </ul>			
<b>Residual Risk of Plant with Control Measures</b>	<ul style="list-style-type: none"> <li>• Acceptable</li> </ul>			
<b>Additional Safety Comments</b>	<ul style="list-style-type: none"> <li>• The risk assessment has been carried out using the NSCA Risk Score Calculator. For more information contact Dingo</li> </ul>			